HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

Three Bears Lake and Dams, East Dam 2,000 feet north of Marias Pass Glacier National Park Village of East Glacier Park vicinity Glacier County Montana HAER No. MT-88-A

MONT 18-EAGLPA!

(The site is also in Flathead County, Village of West Glacier vicinity)

NOTE: Photographs were taken by George McFarland, photographer, August/September 1991

MT-88-A-1 VIEW OF EAST DAM, LOOKING NORTH

MT-88-A-2 DETAIL VIEW SHOWING WOODEN CRIBBING WITH LOWERED LAKE LEVEL, EAST DAM, LOOKING NORTHEAST (View is middle of the perimeter showing in MT-88-A-1 above.)

MT-88-A-3 VIEW SHOWING NORTH END OF EAST DAM, LOOKING NORTH

MT-88-A-4 DETAIL VIEW OF TRIPLE TONGUE AND GROOVE CRIBBING USED IN DAM CONSTRUCTION, NORTH EAST OF EAST DAM, LOOKING NORTH

MT-88-A-5 VIEW OF NORTH END OF EAST DAM, LOOKING SOUTH

MT-88-A-6 VIEW OF NORTH END OF EAST DAM, LOOKING SOUTH. (View is taken from lakeside with lowered water level. This view encompasses the same area as MT-88-A-5 above.)

NOTE: For the history of the East Dam, see HAER No. MT-88, Three Bears Lake and Dam.